Service Bulletin

SB No. LCD04080601N

Original Date	Revised Date	Problem Code	Type Code	Status	Author
AUG 6, 2004	-	CH56	WARR	NEW	SHORT

Subject: Early production LCD Entertainment Tuning

Serial Number: LCD-0101-01 LNB000001-LNB000376, LCD-0201-01 LNG000001-LNG001131

Time Required: ☒15 min ☐30 min ☐45 min ☐1 hr +

Distribute To: ☐Internal ☒Dealer ☒ISO ☐Customer

DESCRIPTION:

Early production LCD Entertainment TV's cannot be tuned into channel 5 or 6.

SOLUTION:

Reprogram TV with GK32-00002-0018 KIT:SERV;MFG;PROG/ENT;NTSC, as shown, and replace Inverter Board GK32-00002-0004.

The Service Kit Includes:

- Entertainment Programmer
- 12.5VDC Power Supply
- Line Cord
- Instruction Sheet

Life Fitness Proprietary and Confidential Information - Only for the Use of the Intended Recipient - Do Not Reproduce or Distribute.